

Hydrogen Incidents and Lessons Learned

Nick Barilo Executive Director, Center for Hydrogen Safety April 17, 2024



CHS Hydrogen Incident Response Activities



Hydrogen Incident Occurs



CHS reaches out through established channels to gather all relevant information

CHS Holds Member Meeting



CHS convenes members to discuss incident and share information

CHS-HSP Participates in Fact Finding



CHS and the
Hydrogen Safety Panel
are available to help
determine cause

CHS Develops Incident Record



CHS creates membersonly incident report to track latest information and lessons learned

CHS Publishes Lessons Learned



Hydrogen Tools

CHS translates information into public lessons learned and publishes on H2Tools.org

Other resources CHS may use for responding to an incident:

- Education Materials new courses, revised course content, etc.
- Technical Bulletins members only and public safety bulletins developed and disseminated
- Working Groups to address important safety issues and develop learnings for community and industry
- Conferences & Workshops share incident information and learnings
- Incident Management Guide

Lessons Learned

Those who cannot remember the past are condemned to repeat it.

- George Santayana

A few benefits of lessons-learned activities:

- It helps an organization understand the root causes of incidents and prevent future occurrences
- ▶ It can help protect finances and reputation
- It enables the industry to consider and evaluate where similar vulnerabilities exist
- Informs standards development organizations
- It is important to support a strong safety culture



HIAD 2.0 DATABASE




Clean Hydrogen Partnership


Results from the statistics analysis (1)

The analysis reported here is based on the 706 incidents, which were in the database as of May 2021. A total of 576 of these events were considered to be statistically relevant and formed the basis for the statistical analysis to inform lessons learned and recommendations.

Years



Industrial sectors






HIAD 2.0 DATABASE




Clean Hydrogen Partnership

Results from the statistics analysis (3)

Operational mode



Causes (multiple entries per incident possible)



European Hydrogen Safety Panel (EHSP)



EUROPEAN PARTNERSHIP

H2Tools Lessons Learned

221 Records spanning 50+ years


A database-driven website to facilitate the sharing of lessons learned and other relevant information gained from actual experiences using and working with hydrogen.


The database also serves as a voluntary reporting tool for capturing records of events involving either hydrogen or hydrogen-related technologies.

It does not reflect all incidents that have occurred, only those reported

Total Record Severity by Setting

To view a breakdown of total cases by different metrics use the filters above.





Stationary Facility Incidents

Tank Explosion at Research Facility





Event Summary

 An outdoor hydrogen tank exploded at a research and development complex during test of a water electrolyzer

Cause

- Ignition of a hydrogen-oxygen gas mixture within the tank resulting in vessel overpressure
 - Electrolyzer cell membrane degradation may have permitted excessive oxygen gas crossover rate through the electrolyzer cell membranes into the product hydrogen gas

Lessons Learned

- Understand interrelation of electrolyzer membrane gas permeability, membrane degradation, and dynamic operating range when establishing process safety controls
- Consider automatic gas storage isolation and stopping gas generation when safety limits are exceeded



EventImpact

- Two fatalities
- Six injuries
- \$30 million damage

Fueling Station Tank Leak, Fire and Explosion





Event Summary

A leak from one tank within a high-pressure hydrogen storage unit serving a hydrogen vehicle fueling station resulted in a jet fire and an open-air deflagration

Cause

- An assembly error of a specific sealing end plug for the high-pressure hydrogen tank
 - The inner bolts of the plug had not been adequately torqued, allowing seal failures to progress into an explosion and subsequent jet fire

Lessons Learned

Implement rigorous assembly, double-witness verification, and documentation/marking procedures for hydrogencontaining equipment



EventImpact

- No injuries
- Station damage
- Airbag activated in nearby vehicle

Hydrogen Plant Truck Fueling Deflagration and Fire



Event Summary

 A gaseous hydrogen leak, fire, and deflagration occurred at a hydrogen production and trailer loading station during a filling operation

Cause

Unauthorized repair and failure to follow procedures during a minor leak resulted in more severe consequences

Lessons Learned

- Repairs must be performed by authorized, trained maintenance personnel following valid procedures
- When two persons are utilized for transfer operations, ensure that equipment configuration is verified before performing critical actions
- Hydrogen deflagration overpressures may cause secondary system leaks and degrade integrity



EventImpact

- No injuries
- Equipment damage
- Four tankers damaged

Bus Fueling Station Fire





Event Summary


➤ A pressure relief valve failed, causing the release of approximately 300 kg (660 lbs.) of hydrogen over approximately 2.5 hours

Cause

An incompatible pressure relief device was installed

Corrective Actions

- Before reopening the station, physical changes were made using the correct pressure relief device (PRD) and higher vent stacks
- New and modified procedures were instituted to improve the timely communication of station status during emergency events
- Additional training of personnel focused on improving the response time and effective communication between employees, first responders, and the hydrogen equipment supplier



Approximate location of cut line to separate nozzle subassembly from inlet base

Event Impact

- No injuries
- Very minor equipment damage
- Extensive evacuation of residents and businesses

H₂ Explosion at a Powdered Metals Plant





- Operators heard a hissing noise near one of the plant furnaces and determined that it was a gas leak in the trench below the furnaces
 - The trench carried hydrogen, nitrogen, and cooling water runoff pipes as well as a vent pipe for the furnaces
- Maintenance personnel incorrectly presumed that the leak was nonflammable nitrogen because there had recently been a nitrogen piping leak elsewhere in the plant
 - A forklift with a chain was used to remove a trench covers to access the piping
- Eyewitnesses stated that as the first trench cover was wrenched from its position by the forklift, friction created sparks followed immediately by a powerful explosion
- ► The investigation revealed a large hole (~3x7 inches) in a corroded section of hydrogen vent piping inside the trench





Top: hole in hydrogen pipe Bottom: cover plates dislodged by explosion

Source: Chemical Safety Board and http://www.h2tools.org/lessons

Transportation Incidents

H₂ Liquid Trailer (14k gallons) is Broadsided







The car and hydrogen trailer after the fire was extinguished

The vehicle recovery team led a safe and successful transfer of all liquid hydrogen from the damaged trailer to another one


- Driver in opposite lane swerved and went across median, slamming into LH₂ trailer
- The gasoline in the car caught fire
- The shell of the hydrogen trailer withstood the impact with no loss of containment



Successful liquid transfer following the accident in Louisiana

H₂ Liquid Trailer Rear Ended at High Speed






The valve used to pull vacuum between the inner and outer shells was damaged. This resulted in a loss of insulation. This and heat from fire increased the temperature of the LH_2 and built pressure, which vented through safety valves as designed.

Total vent time: 30 hours (for 3,000 gallons)

Stationary LH₂ trailer hit by glycerin tanker at high speed. Diesel fire ensued.



Modular Transport Leak and Fire

Event Summary

- Multiple elements of a hydrogen gas module suddenly leaked and caught fire while the transport truck was stopped at a traffic light
- No injuries, but approximately 1,500-2,000 people from surrounding businesses and residential areas were involved in an evacuation

Cause

- Incorrectly rated and incompatible PRDs installed during maintenance activity
- PRD vent tubing compression fittings to some of the gas cylinders had not been sufficiently secured

Lessons Learned

Implement rigorous double-witness verification, and documentation/marking procedures for hydrogencontaining equipment during assembly and maintenance inspections







Traffic Accident Involving H₂ Storage Trailer





- A traffic accident with a passenger vehicle led to loss of control and leaving the roadway at the intersection
 - F350 Dual Rear Wheel tow vehicle
 - Light Duty tri-axle trailer carrying two vessels "tube bundles"
- Impacted traffic light pole and ditch on the side of the roadway
- Full loss of hydrogen containment (240 kg)
- Damage
 - Three minor injuries
 - The trailer and pickup truck were both a total loss from the impact and fire
 - Damage to light pole and overhead wires



Traffic Accident Involving H₂ Storage Trailer






- The method of anchoring the tube bundles to the trailer allowed for movement
 - Movement of bundle combined with gooseneck deformation allowed contact
- Vent piping appears to be insufficiently supported for PRD reaction forces
 - This led to the non-vertical venting of hydrogen
- Trailer and tube bundle frame appear to have been insufficient to protect piping in this accident
 - Line shear plus open valves may have played a role in the initial hydrogen release
 - PRDs may have played a role in the initial hydrogen release
 - Vent piping may have been inadequately restrained to withstand impact
- Ball valves might have failed to provide containment
 - The impact may have opened valves
 - Impact broke the stem of at least one valve
 - Packing/Seals damaged in fire likely led to further leakage
 - Packing/Seals damaged in fire may have allowed valves to open

Liquid Hydrogen Lessons Learned








Trailer Vent System Weather Protection





- The tube trailer was located at a customer location
- Water entered the vent stack
 - Vertical discharge but no caps
 - Weather-related
- Water froze during inclement weather
 - Abnormal for area
- Ice plug pushed against and damaged a rupture disc
 - Rupture disc activated and led to loss of containment
 - The vent system remained in place, minimizing the consequences
 - No ignition, well-sited
 - Must replace remaining devices since they may have been damaged
- Lessons learned
 - Provide weather protection to vent outlets
 - Blockages can also damage relief devices



CNG Incident – February 2024




- A semi-truck's 100-gallon compressed natural gas tank exploded while firefighters attempted to extinguish the flame
 - Nine firefighters were injured during their response to a natural gas-powered semi-truck fire.
- The storage system's similarities to hydrogen highlight the need to ensure first responders have the information necessary to mitigate hydrogen incidents safely
- ► The US National Transportation Safety Board is currently investigating the incident



Video from ABC7, Los Angeles

What Have We Learned?



General Learnings from H₂ Incidents





- Human factors play a significant role in incidents... either causing or significantly contributing to the incident's impacts
 - Implement a strong safety culture
 - Utilize engineering controls before administrative controls



- Share what you have learned from an incident
 - Sharing is needed to help the industry avoid similar incidents, and transparency helps instill public confidence




- Help First Responders minimize the consequences of incidents by providing:
 - Training and knowledge resources for first responders before an incident occurs
 - Prompt information and support to the incident commander to help them understand the fuel and hazards





- Plan ahead for how to respond to an incident
 - Include crisis management and internal/external communication
 - Incident recovery

Hydrogen Incident Recovery Guide

- Published July 2022
- Provides practical guidance with a checklist to help an organization recover from a hydrogen incident and return to normal operations
- Applies to the post-event recovery phase
- The can be tailored to meet the specific needs of the organization









July 2022

Conclusions



Incidents will occur, but let's minimize their frequency and impact


Sharing of information is critical


- Why? It helps everyone and transparency bolsters industry confidence
- For incidents from more than 5 years ago, use the input form on H2Tools at <a href="https://h2tools.org/lessons?search_api_fulltext="https://h2tools.org/lessons.org/l

Information sharing has obstacles

- Barriers to getting information shame, potential litigation, lack of seeing the value
- Barriers to applying learnings how does an organization know about an incident and may not see why they need to consider learnings

The best way to avoid the negative consequences of an incident is to avoid the incident. And remember, if you don't have the resources to prevent an incident, how will you have the resources to recover?





Thanks for Your Attention



Nick Barilo

Executive Director | Center for Hydrogen Safety, AIChE Hydrogen Safety Program Manager | PNNL 120 Wall Street, 23rd Floor

New York, NY USA

Tel: 509-371-7894

nickb@aiche.org

http://www.aiche.org/chs

http://h2tools.org



in LinkedIn: www.linkedin.com/showcase/center-for-hydrogen-safety/



Extra Slides

Other Recent Incidents





- Austria Cylinder Explosion No update
 - Overpressure of 350 bar cylinder from a 900 bar supply source
- Golden Empire bus fire
 - Still under investigation
- Gaseous H2 trailer TPRD activation incidents in Southern California
 - Three separate incidents over a several-month period
 - o During trailer loading resulted in fire and vent system failure
 - o The trailer was parked during a delivery
- H2 bus bridge impact incident in Netherlands https://www.persbureaudrenthe.nl/drenthe/bus-te-hoog-of-brug-te-laat-bij-wijster/
- Hose Issues
 - Reports of at least one H70 dispenser hose failure in Korea
 - o Upon inspection of other sites, additional precursor damage found
 - o Short-term additional inspections have been put in place while additional RCA is being conducted
- Deflagration within a compressor enclosure



Netherlands Bus Accident

A Few Hydrogen Transportation Considerations



- Gas
 - During transport under high-pressure
 - Equipment can be installed or reinstalled incorrectly
 - Must be designed to ensure proper venting during roll-over incident... vent lines on front and back
- Liquid over the road travel time and pressures are important to avoid venting while traveling
 - Tank going liquid full can result in activating rupture disk and discharging liquid
 - Proper vessel design is critical
 - Proper transfer techniques are important
- Minimize impact of accidents during transport
 - Location of manifold and how it is protected
 - Tubes don't move and manifold adequately protected
 - Valves closed during transport
- Fill and transfer activities
 - Issues with hoses
 - Leaks and improper connections



Credit: KTLA

Keep First Responders Informed & Prepared



Goal

 Support the successful implementation of hydrogen and fuel cell technologies by providing technically accurate hydrogen safety and emergency response information to first responders

Integrated Activities

- Online, awareness-level training (https://tinyurl.com/yxfy66rp)
 and video-based training courses (https://tinyurl.com/y64q48ck)
- Classroom and hands-on operations-level training
- Trainer material (PowerPoint slides with speaker notes)



A properly trained first responder community is critical to the successful introduction of hydrogen fuel cell applications and their transformation in how we use energy.